

TEXAS NATURAL RESOURCE
CONSERVATION COMMISSION

P.O. Box 13087

Austin, Texas 78711-3087



9-20-01
U-15

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039.

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. TX0000005384		Manifest Document No. 53080		2. Page 1 of 1		Information in the shaded areas is not required by Federal law.		
3. Generator's Name and Mailing Address US EPA REGION 6 - LONGVIEW REFINERY 1445 Ross Avenue Dallas, TX 75202						A. State Manifest Document Number 02653080				
4. Generator's Phone 817 821-8172						B. State Generator's ID XXX05				
5. Transporter 1 Company Name Com City Cob						C. State Transporter's ID 41015				
6. US EPA ID Number ILD981195720						D. Transporter's Phone 815 634-4773				
7. Transporter 2 Company Name 0						E. State Transporter's ID				
8. US EPA ID Number						F. Transporter's Phone				
9. Designated Facility Name and Site Address PSC CHEMICAL RECLAMATION SERVICES 405 Powell Avalon, TX 76623						G. State Facility's ID 50084				
10. US EPA ID Number TXD046844700						H. Facility's Phone 972 627-3224				
11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, ID Number and Packing Group)					12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	15. Waste No.
X	a. WASTE COMBUSTIBLE LIQUID, N.O.S. COMBUSTIBLE NA1993, PG III ERG# 128 (Benzene, Napthalene) LIQUID.					001	TT	1450	G	AFMW211H D018
	b.									
	c.									
	d.									
J. Additional Descriptions for Materials Listed Above						K. Handling Codes for Wastes Listed Above				
11a. 017625						11b.				
11c. received 11,840						11d.				
						11e.				
						11f.				
15. Special Handling Instructions and Additional Information 24 Hour Emergency Contact Scott St. John (817) 821-8172 Site Address: 601 Premiere Road, Longview, TX 75608										
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packaged, marked, and labelled/placarded, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.										
Printed/Typed Name For L. B. R. EPA (Tad) Wolford						Signature <i>[Signature]</i>			Month Day Year 9/14/01	
17. Transporter 1 Acknowledgement of Receipt of Materials										
Printed/Typed Name LARRY JONES						Signature <i>[Signature]</i>			Month Day Year 09/14/01	
18. Transporter 2 Acknowledgement of Receipt of Materials										
Printed/Typed Name						Signature			Month Day Year	
19. Discrepancy Indication Space										
 825703										
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.										
Printed/Typed Name On Behalf of ACS Grant me...						Signature <i>[Signature]</i>			Month Day Year 09/14/01	

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

- (1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.
- (2) Enter the total number of pages used to complete this manifest.
- (3) Enter the company name and mailing address of the generator of the waste.
- (4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.
- (5) Enter the company name of the first transporter and their U.S. EPA ID Number.
- (6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A) or in box 15 of this form.
- (7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.
- (8) **COMPLETE AND STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS**
- (9) Complete the waste description table as follows:
 - (A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.
 - (B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class or Division, and U.S. DOT Hazardous Waste Identification Number. If it is a Class 1 nonhazardous waste use the Texas Waste Code description.
 - (C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TNRCC Industrial Solid Waste Rules.
 - (D) ITEM 13 - Enter the total quantity of waste described on each line.
 - (E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	
 - (F) ITEM 1 - Enter the appropriate TNRCC State Waste Code for each waste you are shipping.
- (10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.
- (11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.
- * (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

- (1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.
- (2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR**.
- (3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".
- * (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD Facility Owner/Operator**.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

- (1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.
- (2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I**.
- (3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR**.

* U.S. EPA and TNRCC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do **not** send to TNRCC unless otherwise notified by these departments.

BURDEN STATEMENT

The public reporting burden for this collection of information is estimated to average 31 minutes for generators, 16 minutes for transporters, and 16 minutes for treatment, storage and disposal facilities. The recordkeeping burden per response for this collection of information is estimated to average 6 minutes for generators, 6 minutes for transporters, and 6 minutes for treatment, storage and disposal facilities. The burden associated with reading the regulations is estimated at 1 hour and 15 minutes annually. Burden means the total time, effort, or financial resources expended by persons to generate, maintain, retain, or disclose or provide information to or for a Federal agency.

An agency may not conduct or sponsor, and a person is not required to respond to, a collection of information unless it displays a currently valid OMB control number. The OMB numbers for EPA's regulations are listed in 40 CFR Part 9 and 48 CFR Chapter 15. Send comments regarding these burden statements or any other aspect of this collection, including suggestions for reducing the burden, including through the use of automated collection techniques to the Director, OPPE Regulatory Information Division, U.S. Environmental Protection Agency (2137), 401 M St., S.W., Washington, D.C., 20460 and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Attention: Desk Officer for EPA, 725 17th Street, N.W. Washington, D.C. 20503. Include the OMB control number in any correspondence.



Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved QMB No. 2050-00397

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. TX0000005384	Manifest Document No. 53085	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.		
3. Generator's Name and Mailing Address US EPA REGION 6 - LONGVIEW REFINERY 1446 Ross Avenue Dallas, TX 75202				A. State Manifest Document Number 02653085			
4. Generator's Phone (817) 821-8172				B. State Generator's ID XXX05			
5. Transporter 1 Company Name PSC NORTRU TRANSPORTATION		6. US EPA ID Number MID021087275		C. State Transporter's ID 47091			
7. Transporter 2 Company Name PSC		8. US EPA ID Number		D. Transporter's Phone 800 243-8732			
9. Designated Facility Name and Site Address PSC CHEMICAL RECLAMATION SERVICES 405 Powell Avalon, TX 78623		10. US EPA ID Number TXD046844700		E. State Transporter's ID			
				F. Transporter's Phone			
				G. State Facility's ID 50084			
				H. Facility's Phone 972 627-3224			
11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, ID Number and Packing Group)		12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	15. Waste No.
X	a. WASTE COMBUSTIBLE LIQUID, N.O.S. COMBUSTIBLE LIQUID, NA1993, PG III ERG# 128 (Benzene, Naphthalene)		001	TT	4500	G	AFMA211H D018
	b.						
	c.						
	d.						
J. Additional Descriptions for Materials Listed Above 11a. 017626 () 11c. received 39,220 P ()				K. Handling Codes for Wastes Listed Above 11a. M0611D 11b. 11c. 11d.			
15. Special Handling Instructions and Additional Information 24 Hour Emergency Contact: Scott St. John (817) 821-8172 Site Address: 601 Premiere Road, Longview, TX 75608							
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packaged, marked, and labelled/placarded, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.							
Printed/Typed Name Ferton Bisco (Todd Wolford)		Signature <i>Todd Wolford</i>		Month Day Year 09/14/01			
17. Transporter 1 Acknowledgement of Receipt of Materials		Printed/Typed Name Tommy Rickman		Signature <i>Tommy Rickman</i>		Date 09/14/01	
18. Transporter 2 Acknowledgement of Receipt of Materials		Printed/Typed Name		Signature		Date	
19. Discrepancy Indication Space Section 13a. should read "5,402". per Scott St James. G.M.							
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.		Printed/Typed Name Herman Cooper		Signature <i>Herman Cooper</i>		Date 09/14/01	

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

- (1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.
- (2) Enter the total number of pages used to complete this manifest.
- (3) Enter the company name and mailing address of the generator of the waste.
- (4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.
- (5) Enter the company name of the first transporter and their U.S. EPA ID Number.
- (6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A) or in box 15 of this form.
- (7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.
- (8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**
- (9) Complete the waste description table as follows:
 - (A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.
 - (B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class or Division, and U.S. DOT UN Number. If it is a Class I nonhazardous waste use the Texas Waste Code description.
 - (C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TNRCC Industrial Solid Waste Rules.
 - (D) ITEM 13 - Enter the total quantity of waste described on each line.
 - (E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	
 - (F) ITEM I - Enter the appropriate TNRCC State Waste Code for each waste you are shipping.
- (10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.
- (11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.
- (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

- (1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.
- (2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR**.
- (3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".
- (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD Facility Owner/Operator**.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

- (1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.
- (2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I**.
- (3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR**.

* U.S. EPA and TNRCC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TNRCC unless otherwise notified by these departments.

BURDEN STATEMENT

The public reporting burden for this collection of information is estimated to average 31 minutes for generators, 16 minutes for transporters, and 16 minutes for treatment, storage and disposal facilities. The recordkeeping burden per response for this collection of information is estimated to average 6 minutes for generators, 6 minutes for transporters, and 6 minutes for treatment, storage and disposal facilities. The burden associated with reading the regulations is estimated at 1 hour and 15 minutes annually. Burden means the total time, effort, or financial resources expended by persons to generate, maintain, retain, or disclose or provide information to or for a Federal agency.

An agency may not conduct or sponsor, and a person is not required to respond to, a collection of information unless it displays a currently valid OMB control number. The OMB numbers for EPA's regulations are listed in 40 CFR Part 9 and 48 CFR Chapter 15. Send comments regarding these burden statements or any other aspect of this collection, including suggestions for reducing the burden, including through the use of automated collection techniques to the Director, OPPE Regulatory Information Division, U.S. Environmental Protection Agency (2137), 401 M St., S.W., Washington, D.C., 20460 and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Attention: Desk Officer for EPA, 725 17th Street, N.W. Washington, D.C. 20503. Include the OMB control number in any correspondence.